



47 Humphrey Drive
Syosset, NY 11791
516.921.7171

72 Farmedge Road
Levittown, NY 11756
516.490.3301

December 2023

TO: VCLC Families and Staff

FROM: Administration

RE: Notification Letter Concerning Asbestos Content & Management
Plan for the building in Syosset

In 1986, Congress passed the Asbestos Hazard Emergency Response Act. (AHERA). That law requires all schools, kindergarten through twelfth grade, be inspected and identify any asbestos-containing building materials. The law further requires the development of a Management Plan, based upon the findings of the inspection, which outlines our intent in controlling the potential for exposure to asbestos fibers in our schools.

In the past, asbestos was used extensively in building materials because of its insulating and fire retarding capabilities. Virtually any building built before the late 1970's contains at least some asbestos in pipe insulation, structural fireproofing, and floor tiles. Throughout the years, Variety has properly removed any asbestos containing materials that began to deteriorate or became damaged or disturbed during construction. In addition, we continually test the air quality and examine the remaining asbestos containing materials for damage and/or exposure in the Syosset building(s).

Our school has been inspected and some asbestos containing materials were identified in the building. The materials are distributed in various locations and include floor and wall tile, window caulking, and other mechanical areas not readily accessible to building occupants or students.

Your school's Inspection Report and Management Plan outlines in detail the methods used to maintain the materials in a safe manner. In addition, as required by law, appropriate school staff members have been trained to administer this program.

A copy of the inspection report and the management plan is on file in the Director of Facilities office for review if you so desire. If you have any questions, please contact Chris Milano at extension #2248.

Thank you.



47 Humphrey Drive
Syosset, NY 11791
516.921.7171

72 Farmedge Road
Levittown, NY 11756
516.490.3301

Diciembre 2023

A: Familias y Personal de VCLC
DE: Administración
RE: Carta de notificación a cerca del Contenido de Amianto y el Plan de Gestión en el edificio en Syosset

En 1986, el Congreso aprobó la Ley de Respuesta a Emergencias a los Peligros de Asbesto (Asbestos Hazard Emergency Response Act). (AHERA). Esta ley requiere que todas las escuelas, jardín de infantes hasta el duodécimo grado, sean inspeccionadas e identificar materiales de construcción que contienen amianto (asbesto). La ley requiere aún más el desarrollo de un Plan de Manejo, en base a los resultados de la inspección, que describe nuestra intención en el control del potencial de exposición a fibras de amianto en nuestras escuelas.

En el pasado, el amianto se utilizaba ampliamente en los materiales de construcción, debido a sus capacidades de aislamiento e ignífugas. Prácticamente cualquier edificio construido antes de 1970, contiene al menos algo de amianto (asbesto) en el aislamiento de las tuberías, la protección estructural contra incendios y las baldosas del suelo. A lo largo de los años, Variety ha eliminado adecuadamente cualquier material que contiene amianto (asbesto) que se haya comenzado a deteriorarse o que se haya dañado o perturbado durante la construcción. Además, proamos continuamente la calidad del aire y examinamos los materiales restantes que contienen amianto en busca de danos y / o exposición en el edificio en Syosset.

Nuestra escuela ha sido inspeccionada y se han identificado algunos materiales que contienen amianto fen el edificio. Las fibras de amianto (asbesto) fueron encontradas en varios lugares e incluyen el piso, y azulejos, calafateo en algunas ventanas, y otras áreas cuales no son fácilmente accesibles a los ocupantes del edificio o estudiantes.

El Informe de la Inspección y Plan de Manejo esta descrito en detalles, los métodos utilizados para mantener los materiales de una manera segura. Además, tal como lo requiere la ley, los miembros del personal apropiado de la escuela han sido entrenados para administrar este programa.

Una copia del informe de inspección y el plan de manejo se encuentra archivado en la Oficina del Director de Instalaciones para su revisión si así lo desea. Si tiene alguna pregunta, comuníquese con Chris Milano a la extensión # 2131.

Gracias